



**ADVISORY REVIEW BOARD'S VARIANCE AGENDA**

DATE: March 12, 2014 MEETING LOCATION: Conference Call

RECOMMENDATIONS

BOARD DOH FINAL

DOHCHD MOTION VOTE ACTION

AP #	APPLICANT'S NAME AND ADDRESS	COUNTY OF PROJECT	SECTION OF LAW OR RULE AND SPECIFIC VARIANCE(S) REQUESTED	A P R V	D E N Y	A P R V	D E N Y	Y E S	N O	A P R V	D E N Y	PROVISOS RECOMMENDED BY BOARD	PROVISOS REQUIRED BY DOH	DATE LETTER MAILED
------	------------------------------	-------------------	---	------------------	------------------	------------------	------------------	-------------	--------	------------------	------------------	-------------------------------	--------------------------	--------------------

2565	Costa Norte HOA 2580 Sykes Creek Drive Merritt Island, FL  SPA	Brevard	SPA:  64E-9.006(1)(d)3., and 64E-9.010(4) FAC. Step tile to be slip resistant and dark.  64E-9.006(1)(e)2. FAC. Bench edge markings are not dark and not slip resistant and intermediate riser heights are not uniform. The risers exceed 10 inches, but 12 inches allowed in spas.  64E-9.006(1)(d)5. FAC. Figure four hand rail is not over the bottom step and not secured ti the deck.  64E-9.007(1). FAC. Skimmers must meet NSF Standard 50.  64E-9.007(11)(d)5. FAC. There is no automatic water make-up system.  64E-9.007(16) FAC pH feeder missing . 64E-9.005(1) FAC Engineered plans are required.  64E-9.010(13) FAC. ORP required.					X	3	1				
------	--	---------	--	--	--	--	--	---	---	---	--	--	--	--

